

2300 N 2nd St Minneapolis, MN 55411 • Phone 612-529-9671 • Fax 612-529-9670

December 7, 2009

**BONDING DISCLAIMER**

No construction performed solely with adhesives is 100% fail safe. Conditions outside of our control, such as excessive load, whether accidentally or intentionally placed on the completed project, can cause a bond to fail, and Brin Northwestern Glass is by no means responsible for those situations. We therefore have to reject any liability which exceeds the replacement of bonded material. This refers especially to any indirect or consequential loss, damages or expenses. Replacement of bonded material is solely at the discretion of Brin Northwestern Glass.