



Huntington Bank Stadium, located on the University of Minnesota campus, home for the Minnesota Golden Gophers football team.

The Challenge

When one of the large windows inside the President's Suite at Huntington Bank Stadium broke—along with several handrail glass panels in other suites—it presented a unique challenge. The President's Suite window was both oversized and located in a difficult-to-access part of the stadium, requiring careful coordination of crane, lift operators and experienced glaziers to replace the tempered laminated glass.

The Solution

Brin's service team quickly assessed the scope of work, measured for all replacements, and expedited the fabrication of the required glass through trusted vendor partners. Leveraging the strength and experience of our glazing team, 10 glaziers worked together to execute the project efficiently, ensuring the repairs were completed ahead of football season kickoff.

Results Accomplished

Our team safely removed the damaged glass and installed the new pieces seamlessly, restoring the suites to top condition without disruption to stadium operations.



Why was Brin Glass best suited for this project?

The University of Minnesota has trusted Brin for years to handle ongoing glass repair and replacement needs. Our established relationship, combined with our ability to manage complex projects under tight timelines, made us the clear partner to deliver on this project with precision and reliability.

612-529-9671 | www.bringlass.com